

vx4W10, version 121.587 Changelog

```
+-----+  
| vx4W10_d121_p587.iso |  
+-----+
```

Released November 8th, 2019

Major Fixes

AMD Driver

AMD Driver updated to 19.Q3.1. This driver works in conjunction with an update to the graphics card firmware (version number ending in 112, also applied in this OS) to address system instability exacerbated by power state changes.

Driver and firmware updates

Multiple minor driver updates

Deltacast dCare: 1.4 -> 1.4.2

Deltacast dScope: 1.2.11 -> 1.3.1

Intel Network Connections Software: 23.5.2 -> 24.1

LSI Storage Authority: 005.038.000.000 -> 007.010.007.000

MegaSAS RAID: 7.708.12.00 -> 7.710.08.00

Mellanox OF2: 2.10.50010 -> 2.20.50000

Mellanox Firmware Tool: 4.11.0.103 -> 4.12.0.105

VideoMaster Redist: 6.10 -> 6.12.12.0

The installers found in the Extra Utilities folder have also been updated to their latest versions circa August 2019.

Extra Utilities now contains installer for Bulk Rename Utility.

Current known issues

PCI Express Root Port

A large amount of removable devices with names similar to this will be present in the Safely Remove Hardware and Eject Media menu.

Write-caching



disguise Technologies
127-129 Great Suffolk Street
London, SE1 1PP, UK
info@disguise.one
www.disguise.one
+44 020 7234 9840

Write-caching for small files is permanently enabled on the front USB ports only. Writing a file to an external USB drive may produce this behaviour if the file is small enough (less than 1GB). Safely ejecting the drive before removal should help ensure the file is transferred.

Please contact support@disguise.one for feedback and issues